

Oil Field Environmental Incident Summary

Incident: 20160711123008 **Date/Time of Notice:** 07/11/2016 12:30

Responsible Party: Gibsons

Well Operator:

Well Name: Western Area Water Supply Authority

Field Name:

Well File #:

Date Incident: 6/29/2016 **Time Incident:** 03:00

Facility ID Number:

County: MCKENZIE

Twp: 151

Rng: 98

Sec: 26

Qtr:

Location Description: Fresh water depot. Spill went from the loading station down the drain and into the spillway ditch running along the road

Submitted By: Clifton Kerbs

Received By:

Contact Person: Clifton Kerbs
12125 HWY 5 PO Box 189
Crosby, ND 58730

General Land Use: Well/Facility Site

Affected Medium: Topsoil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Tank Overflow

Release Contained in Dike: No

Reported to NRC: Unknown

	Spilled	Units	Recovered	Units	Followup	Units
Oil	3	Barrels	2.5	Barrels		
Brine	1	Barrels				
Other						

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

The oil - water mixture spilled was potentially flammable and may contain hydrocarbons.

Areal Extent:

Approximately 50 ft along the road side ditch and 3 ft wide.

Potential Environmental Impacts:

due to the swift action of the cleanup crew all contamination was removed and clean soil replaced so no future impact will occur from this spill

Action Taken or Planned:

Clean up crew was called in and removed all contaminated soil.

Wastes Disposal Location: the fluid recovered wastes taken to a salt water disposal and the solid wastes were taken to Secure 13 mile landfill disposal

Agencies Involved: Local Law Enforcement

Updates

Date: 7/13/2016 **Status:** Reviewed - Follow-up Required

Author: Souder, Taylor

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the report, the release was not contained. Further follow-up needed.

Date: 9/14/2016 **Status:** Inspection

Author: Schiermeister, Robin

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on site at 10:02 a.m. It was sunny and cool. This site is located a half mile north of Watford City on Hwy 1806. N47.81331 and W103.21887 degrees. No traces of oil and no odors were present. Took conductivity readings with the background between 98 to 180 microsiemens. The release ran into the ditch which had readings of 500 to 804 microsiemens. This is not a concern at this time. No more follow-up is necessary at this time.